



### Project Data

Location	South Texas
Est. Completion	2013
Project Type	Open Top / Internal Floaters
Products / Systems Used	Archco Linings System

### Project Details

A large oil & gas company in South Texas recently had a problem with internal tank corrosion after the pre-existing lining had failed due to old age. Archco 450 was chosen as the tank lining coating due to the excellent reputation for quality products and field service that Denso provides.

The project consisted of two open top/internal floater tanks with the sidewalls coated with Archco 400 high solids epoxy primer and then over coated with Archco 450, 100 % solids epoxy, glass flaked filled lining. All coatings were sprayed with a 68:1 single leg airless unit. The Archco 450 was sprayed at 25 to 30 mils in one coat. The coating was applied prior to the insulation of a new internal floating roof. The Archco 450 will give the tank the chemical resistance, plus the added benefit of the glass flaked filled lining to withstand the abrasion of the floating roof seal, rubbing up and down, as the tank is filled and emptied. The tank floor linings will be installed after the insulation of the floating roof using the Archco 450. The owners can expect 25+ years of internal corrosion protection from the Denso Archco Lining System.

### Benefits

- Fast Dry and Set Time
- Tough Abrasion Resistance
- Cures Under Cool & Damp Climates
- Glass Flake Reinforced
- Good Flexibility & Impact Resistance
- High Build in One Coat - 40 mils
- Excellent Chemical Resistance
- Excellent Adhesion



Open top tank, side walls primed with 400.



Open top tank, side was coated with 400 and 450 gray.



Open top tank, side was coated with 400 and 450 gray.

Date Published: June 2013